Work Order ID 54130

E

Required Date: 08/12/2009

Rib

December 1, 2009 8:47:46 AM



Page 1

Item ID:

D2512-7

Accept

Setup Start

Stop



Revision ID: Item Name:

Start Date:

02/12/2009

QC:

Seart Oty: 4.00

Reg'd Otv: 4.00

Cust Item ID:

Customer:

Reference:

Approvals:

Process Plan:

Tooling:

Run

Start

Stop



Date:

SPC (Y/N):

Date:

Date:

Plan

Code

Reject

Reject

Insp.

Sequence ID/ Work Center ID Draw Nbr

Operation Description Set Up/ Run Hours Draw Number Draw Rev.

Accept Qty

Qty

Stamp Number

100

Revision Nbr

D2512

Rev E

0.00

Large Fab

Large Fab

Large Fab

Memo

0.00

1- Cut as per dwg D2512 - Deburr and remove identification markings on tube

SAD 09-12-02

110

Quality Control

QC5- Inspect part completeness to step on W/O

Memo

Identify as per dwg & Stock Location:

0.00

120

0.00

0.00

09-12-02

Packaging

Packaging

Memo

Dart Aerospace I	∟td
------------------	-----

	•	_							
W/O:			WO	RK ORDER CHAN	GES		-	- 144 +	
DATE	STEP	PRO	OCEDURE CHAN	IGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
			• •						
						, 1			
		•				•		}	
Part No	:	PAR #:	Fault Categ	jory:	NCR: Yes	No DQ	A:	_ Date: _	
	Res	olution:	Disposition) :	QA: N/C (Closed:		Date: _	1-511 744
NCR:			WORK ORDE	R NON-CONFORM	MANCE (NC	R)			
DATE	STEP	Description of NC	Initial	Corrective Action Se Action Description	ection B		cation	Approval	Approval
 		Section A	Chief Eng	Chief Eng	Date		ion C	Chief Eng	QC Inspector
					ļ				
					25				

NOTE: Date & initial all entries

Work Order ID 54130



Page 2

December 1, 2009 8:47:46 AM

Required Date: 08/12/2009

Item ID:

D2512-7

Rib

Revision ID: E

Item Name:

Start Date:

02/12/2009

Operation

Description

Start Oty: 4.00 Rea'd Oty: 4.00



Accept



Setup Start

Stop



Cust Item ID:

Customer:

Draw

Number

Reference:

Approvals:

QC:

Process Plan:

QC21- Final Inspection - Work Order Release

Date:

Date:

Tooling:

SPC (Y/N):

Set Up/

Run Hours

Date:

Draw

Rev.

Date:

Run

Start

Stop

Sequence ID/ Work Center ID

130

Quality Control

Memo

0.00

0.00

Accept

Qty

Plan

Code

Reject Oty

Reject Number

Insp. Stamp

Dart	Aeros	pace	Ltd
------	--------------	------	-----

W/O:			WC	RK ORDER CHANC	GES					
DATE	STEP	PRO	OCEDURE CHAI	NGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
						•				
:										
Part No	•	PAR #:	Fault Cate	gory:		R: Yes	No DQ	4 :	Date:	
		esolution:								
NCR:			WORK ORDI	ER NON-CONFORM	ANCE	(NCR)			
DATE	STEP	Description of NC			tion B		Verific	ation	Approval	Approval
	SILF	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Secti		Chief Eng	QC Inspector
· ·										
		A Company of the Comp								
						٠			· ·	
						<u>.</u>		-	2	
		, and the second			,					

NOTE: Date & initial all entries

Picklist Print

December 1, 2009 8:47:53 AM

Work Order ID: 54130

Parent Item:

Comments:

D2512-7RevE

Parent Item Name: Rib



Start Date: 02/12/2009

Required Date: 08/12/2009

Start Qty: 4.00

Required Qty: 4.00

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Remaining Qty To Pick	Qty Issued	Date Issued	Status
M304TS0.750W.065		Purchased	No		.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	100	f	509.7989	10.7474			
										240	A9-12-	-100

304 SQ Tube .75x.75x.065W

Warehouse	Loc Qty	Loc Code	
Location			
Main Warehouse	•		
MAT	509.7988742		
113082	36.90419		
113245	472.894684		10.7474
Main Warehouse			
WA	0.0000047		
112398	0.0000047		

Page 1

Dart Aerospace Li

W/O:		WORK ORDER CHANGE	ES				
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approva QC Inspector
•							
			,				
				A			

Part No: _	PAR #	: Fault Category:	NCR: Yes No DQA:	_ Date:
	Resolution:	Disposition:	QA: N/C Closed:	_ Date:


NCR:		W	ORK OR	DER NON-CONFORMANCE	(NCR)			
		Description of NC		Corrective Action Section B		Verification	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspector
:					,			
			-	•.				
	,							
			3					
		The state of the s						
							•	

NOTE: Date & initial all entries


PARTS LIST FOR D2512 BASKET LID ASSEMBLY

PART NO	QUANTITY	LENGTH A	LENGTH B	DESCRIPTION
D2512-1	2	· —	√25.50	RIB
D2512-3	2		95.30	RIB
D2512-5	6	30.84		RIB
D2512-7	3	30.63		RIB
D2232-1	2	N/A	N/A	HINGE PLATE
D2236	4	N/A	N/A	RIB
D2327-1	2	N/A	N/A	BUSHING
D2506	1	N/A	N/A	LABEL PLATE
D2581	2	N/A	N/A	MOUNTING BRACKET

SHOPCORY RETURNIO ENGINEER (- G UNCONTROLLED (OP) SUBJECT TO AMEND, LENT WITHOUT NOT! WORK ORDER NO. 54/30 Per 09-12-01









<u>D2512-1/-3/-5/-7 NOTES:</u>
1) MATERIAL: AISI 304/316 SS, 3/4 X 3/4 X 0.065 WALL SQUARE TUBING

0.75 REF

0.75 REF

REF. DART SPEC M304TS0.750W.065

0.065 REF


- 2) FINISH: N/A
- 3) TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NOTED
 4) UNITS: INCHES UNLESS OTHERWISE NOTED
 5) BREAK SHARP EDGES: 0.005 TO 0.010 MAX


- 6) IDENTIFICATION: NONE
- 7) WEIGHT: N/A
- 8) CUT LENGTH/SHAPE PER DIAGRAM AND PARTS LIST

REV.
A
В
С
D
Æ

DESIGN	BW	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
DRAWN	A JS		
CHECKED	.6	DRAWING NO.	REV. E
MFG. APPR.	- 24	D2512s	HEET 1 OF 4
APPROVED	104	TITLE	SCALE
DE APPR.	-1	BASKET LID ASSEMBLY (350/212)	NTS
DATE 09 06 17		COPYRIGHT © 1995 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND COMPRESS THAT IT IS	

08.06.17





TRIM MESH AS REQUIRED TO ALLOW D2232-1 HINGE PLATE TO SIT FLUSH ON FRAME D2232-1 HINGE PLATE DRILL 3/8 HOLE AND (TYP BOTH ENDS) INSTALL D2327-1 USING CLOSEST SPACE IN EXPANDED METAL FOR HOLE LOCATION BOTH ENDS DETAIL E D2327-1 VIEW C-C SIMILAR BOTH END RIBS A5-2 TO CENTER OF BASKET В EXPANDED METAL 4.00 **DETAIL E C6-4** 2X 3 PL DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA BW DESIGN SECTION D-D SAME BOTH CENTER RIBS A4-2 DRAWN CHECKED DRAWING NO. REV. E MFG. APPR. D2512 SHEET 4 OF 4 APPROVED TITLE SCALE BASKET LID ASSEMBLY (350/212) DE APPR. COPYRIGHT @ 1995 BY DART AEROSPACE LTD DATE 08.06.17